



Nordson MEDICAL
805 West 71st Street
Loveland, CO 80538, USA

+1.888.404.5837
+1.970.267.5200
nordsonmedical.com

January 6, 2025

Product Notification – DOC #1726331

Affected Parts: VPB Series of Products

VPB1000050N, VPB1000055N, VPB1000062N, VPB1000079N, VPB1000099N, VPB1000110N

Dear Valued Customer:

You are receiving this notice because your company has purchased one of the Part Numbers listed above in the previous two years. Nordson MEDICAL has elected to streamline its stopcock portfolio to provide best-in-class pricing, lead time and service to its customers. We aim to support customers during this transition with as minimal impact as possible.

Nordson MEDICAL currently offers similar and equivalent stopcocks as suggested alternatives below. Additionally, the alternative stopcocks below are fully ISO 80369-7 compliant, whereas the VPB Series of Products were not.

If you have any additional technical questions, please contact your Sales Account Manager or our customer service team at orders@nordsonmedical.com. We appreciate your business and want to thank you for choosing Nordson MEDICAL.

Discontinued P/N	Nordson Suggested Alternative	Notes
VPB1000050N	FCVFMR-001 + FTLLP-6005	Will need to purchase the stopcock and female luer plug separately.
VPB1000055N	FCVFM-001	Fully equivalent
VPB1000062N	FCVFFM-008	Fully equivalent
VPB1000079N	FCVFFM-008 + FTLLP-6005	Will need to purchase the stopcock and female luer plug separately.
VPB1000099N	FCVFFM-008 + FTLLP-6005	Stopcock is 3-way (not 4-way). Will need to purchase the stopcock and female luer plug separately.
VPB1000110N	FCVFFMR-008 + FTLLP-6005	Stopcock is 3-way (not 4-way). Will need to purchase the stopcock and female luer plug separately.

Sincerely,

Jordan Berkel
Product Line Manager
Nordson MEDICAL